

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




Figure 1

TITLE: Mirror For Improved Visibility Of Danger  
Zone Area On Right Side Of School Buses  
INVENTOR: Gloria Buley  
APPLICATION NO.: Not yet assigned,  
CONF. NO. : DOCKET NO. 15328US01  
ATTORNEY: RHS, PHONE: 312-775-8000






FIG 2

TITLE: Mirror For Improved Visibility Of Danger  
Zone Area On Right Side Of School Buses  
INVENTOR: Gloria Buley  
APPLICATION NO.: Not yet assigned,  
CONF. NO. : DOCKET NO. 15328US01  
ATTORNEY: RHS, PHONE: 312-775-8000






Figure 5

TITLE: Mirror For Improved Visibility Of Danger  
 Zone Area On Right Side Of School Buses  
 INVENTOR: Gloria Buley  
 APPLICATION NO.: Not yet assigned,  
 CONF. NO. : DOCKET NO. 15328US01  
 ATTORNEY: RHS, PHONE: 312-775-8000

